

CENTER 310/311

Humidity Temperature Meter (Dual Input, PC Interface) (เครื่องวัดค่าความชื้น-อุณหภูมิ)



FEATURES

- Dual Input (311)
- Triple Display
- PC Interface
- Timer Function (310)
- REL Function (311)
- Auto Power Off
- Hold Function
- Max/Min Function
- Resolution 0.1 °C, 0.1 °F, 0.1%RH

310 Single Input

311 Dual Input

SPECIFICATIONS

Range & Accuracy	Temperature : -20~60 °C..±0.7 °C -4~140 °F..±1.4 °F
	(K-Type) : -200~1370 °C..±0.3%rdg + 1 °C -328~2498 °F..±0.3%rdg + 2 °F
Humidity	0~100%RH..±2.5%RH
Input Protection	60 V DC or 24 Vrms AC Maximum
Battery	9 V battery
Dimensions	Meter : 186 x 64 x 30 mm
	Probe : 190 (L) x 15 (Dia) mm
Weight	Approx. 320 g

CENTER 313/314

Humidity Temperature Meter (Dual Input, PC Interface)
(เครื่องวัดค่าความชื้น-อุณหภูมิพร้อมเก็บข้อมูลในตัว)

FEATURES

- Dual Input (314)
- Triple Display (314)
- PC Interface
- 16,000 Records Data Logger Per Channel
- Auto Power Off
- Clock Function
- Hold Function
- Max/Min Function
- Resolution 0.1 °C, 0.1 °F, 0.1%RH

313 Single Input

314 Dual Input

SPECIFICATIONS

Range & Accuracy	Temperature : -20~60 °C..±0.7 °C -4~140 °F..±1.4 °F
	(K-Type) : -200~1370 °C..±0.3%rdg + 1 °C -328~2498 °F..±0.3%rdg + 2 °F
Humidity	0~100%RH..±2.5%RH
Input Protection	60V DC or 24Vrms AC Maximum
Battery	9V battery
Dimensions	Meter : 186 x 64 x 30mm
	Probe : 190 (L) x 15 (Dia) mm
Weight	Approx. 320g

CENTER 315

Compact Size Humidity Temperature Meter (เครื่องวัดค่าความชื้น-อุณหภูมิ)



FEATURES

- Fast Response Time
- Auto Shut Off For Battery Saving
- REL Function
- Max/Min Function
- Dual Displays:
Primary Display For Humidity;
Secondary Displays For Temperature

SPECIFICATIONS

Range	Temperature : -20~60 °C; -4~140 °F; Humidity: 0~100%RH
Accuracy	±0.8 °C , 1.6 °F ±3%RH
Resolution	0.1 °C; 0.1 °F; 0.1%RH
Operation Temp	0 °C~40°C (<80%RH)
Storage Temp	-10 °C~60 °C (<70%RH)
Battery	9V battery
Dimensions	240 x 54 x 34mm
Weight	Approx. 220g